


# FREESTALL LOOP INSTALLATION

Now You Can Choose Which Option is Best for You!

## OPTION 1

### NO WELDING REQUIRED


For Any Style Loop



LOOP HOLDER  
One per Loop



CROSS HOLDER  
One every 10'



With the Cross Holder and Loop Holder NO Welding is needed to install your Loops, just insert holder on 2 7/8" pipe runner and insert Loop into Holder.

## OPTION 2

### U-BOLTED CLAMP SLEEVE



BOTTOM VIEW



TOP VIEW




FIXED LOOP - No Welding Required

## OPTION 3



FIXED LOOP



TWO-IN-ONE SLEEVE - One Per Loop

INSTALL YOUR LOOPS IN HALF THE TIME WITH MINIMUM WELDING USING THE TWO-IN-ONE SLEEVE

DASILVEIRA SOUTHWEST, INC.

1-800-687-0843

PATENT PENDING

# **NEW FREESTALL LOOP INSTALLATION** **NO SLEEVE & NO WELDING NECESSARY**




**Mounted Loop-No Sleeve & No Welding Required**



**Bottom Mount**

**Top Insertion**



**Top Left**

**Top Right**

**Bottom Left**

**Bottom Right**



**Mounting Piece**

**Top of Mount**

**Bottom of Mount**